
NOTICE TO MARINERS

No. H. 156/2025

H U M B E R A P P R O A C H E S
INNER TRAFFIC SEPARATION SCHEME (INBOUND LANE) -
SHOAL WATER

MARINERS ARE WARNED that a surveys carried out between 9th August 2023 and 29th September 2025 show the following: -

- 1) Depths of between 8.0 metres below Chart Datum and 10.7 metres below Chart Datum have encroached up to 185 metres into the Northern buoy-line of the precautionary area of the Traffic Separation Scheme (TSS), from 370 metres North-East of the Spurn Light Float to the Spurn Light Float

Deeper water exists to the South in this vicinity.
- 2) Depths of between 6.3 metres below Chart Datum and 10.7 metres below Chart Datum have encroached up to 61 metres into the Northern buoy-line of the Inward Traffic Separation Scheme (TSS) Lane, from 730 metres West-South-West of the Spurn Light Float to the Spurn Light Float

Deeper water exists to the South in this vicinity
- 3) Depths of between 7.8 metres below Chart Datum and 10.7 metres below Chart Datum have encroached up to 160 metres into the Northern buoy-line of the Inward Traffic Separation Scheme (TSS) Lane, from 1990 metres East-North-East of the No. 3 Chequer Buoy to 420 metres East-North-East of the No. 3 Chequer Buoy

Deeper water exists to the South in this vicinity
- 4) Depths of between 6.9 metres below Chart Datum and 10.7 metres below Chart Datum have encroached up to 780 metres into the Southern buoy-line of the Inward Traffic Separation Scheme (TSS) Lane, from 2000 metres East-North-East of the Alpha Buoy to 1040 metres East of the Bravo Buoy.

Deeper water exists to the North in this vicinity.

MARINERS ARE ADVISED to navigate with caution in this area and Notice to Mariners No. H. 104/2023 is hereby cancelled.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

3rd November 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com