
NOTICE TO MARINERS

No. H. 171/2025

RIVER HUMBER

HALTON MIDDLE - SHOAL WATER

MARINERS ARE WARNED that surveys carried out between the 17th September to 3rd December 2025 show the following: -

- 1) Depths of between 5 metres and 5.5 metres below Chart Datum have encroached up to 160 metres into the Eastern edge of the channel from 460 metres to 670 metres downstream of the No. 15A Light Buoy.

Deeper water exists to the West in this vicinity.

- 2) A least depth of 5.5 metres below Chart Datum exists mid-channel 125 metres upstream of the No.15A Light Buoy.
- 3) A least depth of 5.4 metres below Chart Datum exists mid-channel 366 metres upstream of the No.15A Light Buoy.
- 4) A least depth of 5.5 metres below Chart Datum exists mid-channel in the vicinity of the No. 17 North Holme Light Float.
- 5) Depths of between 4.7 metres and 5.5 metres below Chart Datum have encroached up to 75 metres into the Western edge of the channel from 370 metres downstream to 830 metres upstream of the No. 14 Skitter Haven Light Buoy.

Deeper water exists to the East in this vicinity.

MARINERS ARE ADVISED that 5.4 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 164/2025 is hereby cancelled.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

3rd December 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com