
NOTICE TO MARINERS

No. H. 122/2025

RIVER HUMBER

GRIMSBY MIDDLE DEPOSIT
SHOAL WATER

MARINERS ARE WARNED that surveys carried out between the 3rd and 5th September 2025 show the following: -

A shoal with a least depth of 1.3 metres below Chart Datum exists in the South-East corner of the Grimsby Middle deposit spoil ground 518 metres downstream of the P7 Light Buoy.

MARINERS ARE ADVISED that depths within spoil grounds are inevitably subject to change and should therefore proceed with caution in these areas. In addition, Notice to Mariners No. H. 54/2025 is hereby cancelled.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

9th September 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com