
NOTICE TO MARINERS

No. H.147/2025

RIVER HUMBER

BULL CHANNEL - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 7th October 2025 shows the following:-

- 1) Depths of between 3.7 metres and 5.5 metres below Chart Datum have encroached up to 430 metres into the Southern edge of the channel, from 1100 metres upstream of the Bull Light Float (North Cardinal) to 290 metres downstream of the Bull Sand Light Buoy.

Deeper water exists to the North in this vicinity.

- 2) A shoal with depths of between 3.7 metres and 5.5 metres below Chart Datum extends from 1025 metres upstream of the Bull Light Float (North Cardinal) to 200 metres upstream of the Bull Sand Light Buoy.

MARINERS ARE ADVISED that Notice to Mariners No. H. 93/2025 is hereby cancelled.

**CAPT. A. FIRMAN.
HARBOUR MASTER, HUMBER**

10th October 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com