

NOTICE TO MARINERS

No. H. 78/2025 <u>UPPER HUMBER</u> MOVES OF FLOATING MARKS AND SHOAL WATER

NOTICE IS HEREBY GIVEN that it is proposed on Thursday 19th June 2025 (or as soon after as circumstances permit) to move: -

- The Middle Whitton Light Float to the following position: Latitude 53° 42.335' N, Longitude 0° 34.084' W (WGS 84) (71 metres East of its current position)
- 2) The Upper Whitton Light Float to the following position: Latitude 53° 43.246' N, Longitude 0° 36.297' W (WGS 84) (47 metres North of its current position)
- 3) The No. 32C Light Buoy to the following position: Latitude 53°43.167' N, Longitude 0° 37.116' W (WGS 84) (52 metres North of its current position)

MARINERS ARE WARNED that on completion of the above moves the following shoal water will exist: -

- 1) A least depth of 1.7 metres **ABOVE** Chart Datum exists North of the ships course 322 metres downstream of the Lower Whitton Light Float.
 - Deeper water exists on the ships course in this vicinity.
- 2) A least depth of 0.2m <u>ABOVE</u> Chart Datum exists North of the ships course 100 metres upstream of the Cappers West Light Float.
 - Deeper water exists on the ships course in this vicinity.
- 3) A least depth of 0.1m <u>ABOVE</u> Chart Datum exists South of the ships course 370 metres upstream of the Middle Whitton Light Float.
 - Deeper water exists on the ships course in this vicinity.
- 4) Depths of between 0 metres at Chart Datum and 0.2 metres <u>ABOVE</u> Chart Datum exist close South of the ships course from 325 metres downstream to 310 metres upstream of the No. 32C Light Buoy.
 - Deeper water exists on the ships course in this vicinity.

- 5) Depths of between 0 metres at Chart Datum and 0.2 metres <u>ABOVE</u> Chart datum exist North of the ships course from 300 metres upstream of the No. 32C Light Buoy to 600 metres downstream of the No. 34 Light Buoy.
 - Deeper water exists on the ships course in this vicinity.
- 6) A least depth of 1.4m **ABOVE** Chart Datum exists North of the ships course in the vicinity of the No. 34 Light Buoy.
 - Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that on completion of the above moves, 0 metres at Chart Datum should be used for passage planning purposes and that Notice to Mariners No. H. 77/2025 will be hereby cancelled.

CAPT. A. FIRMAN HARBOUR MASTER, HUMBER

18th June 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com