
NOTICE TO MARINERS

No. H. 94/2025

RIVER HUMBER
GRIMSBY MIDDLE - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 10th July 2025 shows the following: -

- 1) Depths of less than 6.4 metres below Chart Datum have encroached up to 30 metres into the Northern edge of the navigation channel from the No. 5A Light Buoy to 150 metres upstream of the No. 5A Light Buoy.

Deeper water exists to the South in this vicinity.

- 2) Depths of less than 6.4 metres below Chart Datum have encroached up to 60 metres into the Southern edge of the navigation channel from 455 metres to 1166 metres downstream of the No. 4B Light Buoy.

Deeper water exists to the North in this vicinity.

- 3) Depths of less than 6.4 metres below Chart Datum have encroached up to 75 metres into the Southern edge of the navigation channel from 238 metres upstream of the No. 6 Lower Burcom Light Float to 975 metres downstream of the Pyewipe Outfall Light Buoy.

Deeper water exists to the North in this vicinity.

- 4) Depths of less than 6.4 metres below Chart Datum have encroached up to 60 metres into the Southern edge of the navigation channel from 414 metres to 735 metres upstream of the Pyewipe Outfall Light Buoy.

Deeper water exists to the North in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 29/2025 is hereby cancelled.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

11th July 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com