

---

# **NOTICE TO MARINERS**

---

**No. H. 114/2025**

## **R I V E R   H U M B E R**

### **4A CLEE NESS LIGHT FLOAT RETURNED TO STATION**

**NOTICE IS HEREBY GIVEN** that after scheduled maintenance the 4A Clee Ness Light Float has been returned to station in its original charted position and the temporary buoy has been removed.

The red Catamaran Light Float exhibits the following characteristics:

Latitude – 53° 35.015' N, Longitude 0° 01.670' E

Light Characteristic – FL(2).R.10s

**MARINERS ARE ADVISED** that Notice to Mariners No.H.100/2025 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

18<sup>th</sup> August 2025

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.  
[www.humber.com](http://www.humber.com)