

# **NOTICE TO MARINERS**

No. H. 118/2025

## RIVER HUMBER

### **SKITTER CHANNEL**

#### **MOVE OF FLOATING MARK AND SHOAL WATER**

**NOTICE IS HEREBY GIVEN** that it is proposed on Thursday 28<sup>th</sup> August 2025 (or as soon after as circumstances permit) to move: -

The Hull Middle Light Buoy to the following position:

Latitude 53° 43.560' N, Longitude 0° 18.236' W (WGS 84)

(65 metres South of its current position)

**MARINERS ARE WARNED** that on completion of the above move the following shoal water will exist: -

1) Depths of between 0.6 metres and 2 metres below chart datum exist North of the ships course from 600 metres downstream to 40 metres upstream of the Hull Middle Light Buoy.

Deeper water exists on the ships course in this vicinity.

- 2) A least depth of 1.4 metres below chart datum exists close South of the ships course 520 metres downstream of the No. 20 A Light Buoy.
  - Deeper water exists on and to the North of the ships course in this vicinity.
- 3) A least depth of 1.6 metres below chart datum exists South of the ships course 460 metres upstream of the No. 21B Light Buoy.

Deeper water exists on the ships course in this vicinity.

**MARINERS ARE ADVISED** that on completion of the above move Notice to Mariners No. H. 116/2025 will be cancelled.

#### CAPT. A. FIRMAN HARBOUR MASTER, HUMBER

27th August 2025

#### THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com