
NOTICE TO MARINERS

No. H. 160/2025 U P P E R H U M B E R

SHOAL WATER

MARINERS ARE WARNED that surveys carried out the 10th and 11th November 2025 show the following:

- 1) A least depth of 0.7 metres below Chart Datum exists South of the ships course 370 metres downstream of the No. 29 Light Float.
- 2) A least depth of 0.9 metres below Chart Datum exists near the ships course 210 metres downstream of the No. 29 Light Float.

Deeper water exists on the ships course in this vicinity.

- 3) A least depth of 0.9 metres below Chart Datum exists on and to the South of the ships course from 390 metres to 690 metres downstream of the No. 30 Light Float.

Deeper water exists to the North of the ships course in this vicinity.

- 4) A least depth of 1.5 metres **ABOVE** Chart Datum exists close North of the ships course 400 metres downstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 5) Depths of between 0 metres at Chart Datum and 0.4 metres **ABOVE** Chart Datum exist North of the ships course from 75 metres to 400 metres downstream of the Middle Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 6) A least depth of 0.6 metres below Chart Datum exists in the navigable channel from 620 metres upstream of the No. 32C Light Buoy to 470 metres downstream on the No. 34 Light Bouy.

- 7) A least depth of 0.3 metres **ABOVE** Chart Datum exists close North of the ships course 320 metres downstream of the No. 34 Light Bouy.

Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that 0 metres at Chart Datum should be used for passage planning purposes and that Notice to Mariners No. H. 159/2025 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

11th November 2025

LOCAL NOTICE TO MARINERS FOR 2021, 2022, 2023, 2024 & 2025 CURRENTLY IN FORCE:

H. 07/2021, H. 43/2021, H. 92/2021, H. 109/2021, H. 28/2022, H. 131/2022, H. 52/2023, H. 112/2023, H.76/2024,
H. 149/2024, H. 01/2025, H. 02/2025, H. 07/2025, H. 09/2025, H. 10/2025, H. 14/2025, H. 25/2025, H. 41/2025, H. 43/2025, H.
50/2025, H.51/2025, H. 52/2025, H. 59/2025, H. 65/2025, H. 68/2025, H.70/2025, H. 78/2025 H.79/2025, H. 80/2025, H. 94/2025,
H. 98/2025, H. 101/2025, H. 103/2025, H. 110/2025, H. 112/2025, H. 114/2025, H. 118/2025, H. 121/2025, H. 122/2025, H. 125/2025,
H. 127/2025, H. 136/2025, H. 137/2025, H. 138/2025, H. 141/2025, H.144/2025, H. 146/2025, H. 147/2025, H. 148/2025,
H. 149/2025, H. 151/2025, H. 152/2025, H. 155/2025, H. 156/2025, H. 158/2025, H. 160/2025.

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com